

June 11, 2019


## GM Gen. 1 & Gen. 2 6T70, 6T75, 6T80 Identification Guide

Questions? Email Sonnax Tech Support about this article.



**Lower Valve Bodies** 










**Solenoid Dampers** 









## **Related Units**

6T70 (Gen. 1) Transmission	
6T75 (Gen. 1) Transmission	
6T75 (Gen. 2) Transmission	
6T80 (Gen. 2) Transmission	
6T70 (Gen. 2) Transmission	

## **Related Parts**

6T70 (Gen. 1), 6T75 (Gen. 1)

Zip Kit® (www.sonnax.com//parts/3757-zip-kit) 6T70-ZIP

**Helps cure:** Burnt clutches • Line pressure instability • Loss of fuel economy • No line rise • Pressure loss • Shift concerns • TCC apply & release concerns • TCC codes • Pressure switch codes



6T70 (Gen. 2), 6T75 (Gen. 2), 6T80 (Gen. 2)

Zip Kit (www.sonnax.com//parts/4814-zip-kit) 6T70-G2-ZIP

**Helps cure:** Burnt clutches • Line pressure instability • Loss of fuel economy • No line rise • Pressure loss • Shift concerns • TCC apply & release concerns • TCC codes





While Sonnax makes every effort to ensure the accuracy of technical articles at time of publication, we assume no liability for inaccuracies or for information which may become outdated or obsolete over time.